

SIL



TEST REPORT NO:045293

Date:06 July 2009

LOWS OF DUNDEE LTD MARRBANK HOUSE 6 PARADISE ROAD DUNDEE DD1 9JZ

The following sample(s) was/were submitted and identified by/on behalf of the client as:

Retailer

Description of article Retailer style number Retailer Standard Number Order No./ Buyer Fabric / Yarn Quality Date Sample(s) Received: Unknown 0.5mm Clear Glass Unknown Unknown SUE Unknown 19 June 2009

Result Summary/Conclusion

Test BS 7837:1996

Remarks

Tests as requested by the customer

Signature

rrison Laboratory Manager

For and on behalf of SGS Leicester Ltd.

This document is issued by the Company under its General Conditions of Service accessible at www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law." Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only

200.

Customer: Lows of DUNDEE LTD

Test Report No: 045293

Test method: BS 5438:1989 Test 2B (Bottom edge ignition) with filter paper Flame application time = 10s Trimmed edge Material appears symetrical

Cleansing pre-treatment :

Water soaked according to BS 5651:1989 Clause 3

Summary of Results

"These results were obtained using the specified test conditions and do not necessarily represent the behaviour of the test material under other conditions of test or use.

Specimen	1↑.	2↑	3 ↑	4→	5 ←	6→
Duration of flaming, s	0	0	0	0	1	1
Duration of afterglow,s	0.	0	0	0	0	0.
Flaming debris	No	No	No	No	No	No
Flame to edge	No	No	No	No	No	No
Glow to edge	No	No	No	No	No	No
Max damaged length, mm	12	22	20	20	17	15 .
Ignition of filter paper	No	No	No	No	No	No

Assessment:

BS 7837:1996 Requirements

The sample shall be deemed to perform satisfactorily (pass), if, for at least five of the six test specimens: (a) the duration of flaming does not exceed 5s after removal of the igniting flame; and (b) the lowest boundary of any flame does not reach the upper or either vertical edge; and (c) the filter paper does not smoulder or flame,

This clear "glass" material complies with the requirements of BS 7837:1996.

*This test was sub contracted.

End of Report

This document is issued by the Company under its General Conditions of Service accessible at www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law." Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only